

ILLEGIB

Approved For Release 2001/03/30 : CIA-RDP78T05439A000300060015-0

Approved For Release 2001/03/30 : CIA-RDP78T05439A000300060015-0

Declass Review by NIMA/DOD

~~SECRET NOFORN~~

IB - 2/64
2 January 1964
Copy 1

MEMORANDUM FOR: Chief, Manufacturing and Services Division, ORR

25X1A ATTENTION : [REDACTED]
THROUGH : Chief, Requirements Branch, Reconnaissance Group, CGS
FROM : Chief, CIA/PID (NPIC)
SUBJECT : Various Communist Chinese Cement Plants
REFERENCES : (1) ORR Requirement No. C-RR3-80,697
(2) CIA/PID Project No. C 1467/63

1. This memorandum is in answer to the above referenced requirement which requested annotated photographic enlargements of various Communist Chinese
25X1C Cement Plants which were covered on [REDACTED]

2. In answer to the requirement, a table titled "Partial Listing of Cement
25X1C Plants from [REDACTED] has been attached. This table lists the
plants requested and indicates the information obtained on these plants from
25X1C [REDACTED]

3. The analyst on this project was [REDACTED] who may be contacted
25X1A on extension 2546, should you have further questions regarding this project. This
is considered a completed answer to the requirement.

25X1A [REDACTED]

ENCLOSURES:

7 Annotated Enlargements (CIA/PID/IB-P-878)
1 Table

S-10516

~~SECRET NOFORN~~

GROUP 1
Excluded from automatic
downgrading and
declassification

SECRET NOFORN

PARTIAL LISTING OF CEMENT PLANTS

25X1C

25X1C

<u>LOCATION</u>	<u>NAME</u>	<u>DESCRIPTION</u>	<u>ENLARGEMENTS</u>
Dairen, Liaoning	Ta-lien Cement Plant	Plant not observed due to cloud cover	None
Anshan, Liaoning	Anshan Cement Plant	Plant was not emitting smoke at the time of photography, but freight cars can be seen at the loading platform, and white dust can be observed on the silos and the roof of the finished products building. Therefore it appears that in [REDACTED] the plant was shipping cement, but not producing it.	CIA/PID/IB-P-878/63 25X1D
Around Liao-yung, Liaoning	Hsiao-T'un Cement Plant	This plant could not be located	None
Pen-ch'i, Liaoning (2 plants)	Pen-chi Cement Plant	Due to the amount of dust observed and smoke emanating from its stacks, the plant appears to be in operation.	CIA/PID/IB-P-879/63
	Kung-yuan Cement Plant	Plant did not appear to be in operation at the time of photography.	CIA/PID/IB-P-880/63
Ch'i-chi-ha-erh, Heilungkiang	Chi-Chi-Ha-erh Cement Plant	This plant could not be located.	None
Harbin, Heilung-Kiang	Harbin Cement Plant	At the time of photography this plant was in operation	CIA/PID/IB-P-881/63
Kirin, Kirin	Kirin Cement Plant	This plant could not be located	None

SECRET NOFORN

SECRET NOFORN

25X1C

<u>LOCATION</u>	<u>NAME</u>	<u>DESCRIPTION</u>	<u>ENLARGEMENTS</u>
K'un-ming, Yunnan (2 Plants)	Hai-K'ou Cement Plant	Plant was not in operation in [REDACTED]	CIA/PID/IB-P-882/63 25X1D
	K'un-ming Cement Plant	One stack was smoking, and therefore the plant was, at least, in partial production in [REDACTED]	CIA/PID/IB-P-883/63 25X1D
Liu-Chou, Kwangsi	Liu-Chou Cement Plant	This plant was not in operation in [REDACTED]	25X1D 25X1D

SECRET NOFORN

SECRET NOFORN

AN-SHAN CEMENT PLANT
41° 08'N - 122° 59'E

25X1C

CIA/PID/IB-
P-878/63

SECRET/NOFORN


SECRET NOFORN

PEN CH'I CEMENT PLANT
41° 18' N - 123° 45' E

25X1C

CIA/PID/IB-
P-879/63

SECRET/NOFORN



SECRET NOFORN


KUNG-YAAN CEMENT PLANT
41° 16'N - 123° 43'E

25X1C

CIA/PID/IB-
P-880/63

SECRET/NOFORN

SECRET NOFORN



HARBIN CEMENT PLANT
45° 50'N - 126° 43'E

25X1C

CIA/PID/IB-
P-881/63

SECRET NOFORN

SECRET NOFORN




HAI-K'OU CEMENT PLANT
24° 47'N - 102° 37'E

25X1C

CIA/PID/IE-
P-882/63

SECRET NOFORN



SECRET NOFORN

KUN-MING CEMENT PLANT
25° 00'N - 102° 37'E

25X1C

CIA/PID/IB-
P-883/63

SECRET NOFORN

SECRET NOFORN

LIU-CHOU CEMENT PLANT
24° 22'N - 109° 15'E

25X1C

CIA/PID/IB-
P-884/63

SECRET/NOFORN